

United States Patent [19]

Perlman et al.

[11] Patent Number: 4,994,785

[45] Date of Patent: * Feb. 19, 1991

[54] HOOD ORNAMENT ALARM

[76] Inventors: Marvin K. Perlman, 6138 Caminito Pan, San Diego, Calif. 92120;
Richard I. Perlman, 3852 Casta Bella Dr., La Mesa, Calif. 92041

[*] Notice: The portion of the term of this patent subsequent to Nov. 21, 2006 has been disclaimed.

[21] Appl. No.: 444,989

[22] Filed: Dec. 4, 1989

Related U.S. Application Data

[63] Continuation-in-part of Ser. No. 341,632, Apr. 21, 1989, Pat. No. 4,882,563.

[51] Int. Cl.⁵ B60Q 1/00

[52] U.S. Cl. 340/426; 307/10.2;
340/568

[58] Field of Search 340/426, 429, 568, 571,
340/572, 668, 686, 687; 116/33; 362/80;
307/10.2; 180/287

[56] References Cited

U.S. PATENT DOCUMENTS

4,137,521 1/1979 Martinez 340/568
4,293,860 10/1981 Iwata 340/429
4,882,563 11/1989 Perlman et al. 340/426

Primary Examiner—Joseph A. Orsino

Assistant Examiner—Brent A. Swarthout

Attorney, Agent, or Firm—Ralph S. Branscomb

[57] ABSTRACT

A Mercedes Benz hood ornament structure is modified to include an alarm actuator switch connected to the vehicle horn. The spring-loaded restraint which holds the hood ornament element in its upright position is affixed with a sliding contact which rises into contact with a fixed contact when the hood ornament is deflected forwardly. The two contacts are wired into the horn circuit so that the horn is actuated when the ornament element is deflected forwardly, and the geometry of the mounting for the hood element is such that deflections rearwardly and sideways, such as might occur by accident or in a car wash, will not actuate the horn.

6 Claims, 2 Drawing Sheets

